

Lat/1st

CUSTOMER #: 1477

228191



INVOICE

299 Warren Avenue
Portland, ME 04103
Tel. (207) 797-7837
1-800-464-6225



PORTLAND SAFE CONSULTING & DESIGN IN
3 MALLISON FALLS ROAD
WINDHAM, ME 04062
HOME:207-893-1800 CONT:N/A
BUS: CELL:

PAGE 1

www.oconnorgmc.com

SERVICE ADVISOR: 309 GEORGE CORLISS

COLOR		YEAR	MAKE/MODEL		VIN	LICENSE	MILEAGE IN/ OUT		TAG
		03	STERLING ACTERRA		2FZACFAK83AL99671		179529/179529		
IN SERVICE DATE		PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE	
16AUG11 DD				19:00 16AUG11	PHIL	93.00	CHG	31AUG11	
R.O. OPENED			READY		OPTIONS: DLR:33611 ENG:Cat 3126/CFE DSL 7.2L				

06:38 16AUG11 10:48 31AUG11

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUST SAYS, ENGINE BLOWS BLACK SMOKE AND SKIPS , WARM OR COLD?

H100 DIAG COMPLAINT , REMOVE CYL HEAD

,RE-INSTALLED HEAD ,INSTALLED REMAN ENGINE

412CPPFT 40.00

1	20R0017	ENG AR			24924.94	13700.00	13700.00
	CORE CHARGE C					2200.00	2200.00
1	2104*10723710*	ANGLE, SPRING CLUTCH			1257.33	562.78	562.78
1	15538162	BEARING			41.68	29.18	29.18
1	6D1004	GASKET			2.18	1.31	1.31
1	3918754	GASKET			3.18	1.88	1.88
1	745*236577N*	GOV GASKET			1.68	0.85	0.85
2	88862650	CLEANER			6.82	4.09	8.18
1	8726*3500015*	ENGINE HEATER, 1000W 120V			137.28	52.72	52.72
1	5166*59235*	PERMATEX HIGH TEMPERATURE			15.50	9.30	9.30
1	1P0436	GASKET			1.64	0.98	0.98
1	4088	FILTER COOL			163.91	87.42	87.42
1	5-70-28X	STRAP KIT			16.00	8.53	8.53
1	83AX870	CLAMP			24.62	14.77	14.77
1	FG-AF4878	AIR FILTER			89.60	26.88	26.88
2	20705898	CLAMP			24.46	14.68	29.36
1	20705901	CLAMP			26.16	15.70	15.70
1	05-16516-001	PIPE HTR			604.08	322.18	322.18
1	FR FREIGHT				30.00	30.00	30.00
6	FG-CC2551	HD EG CONC 1 GAL			59.68	17.90	107.40
-1	20R0017	CORE RETURN			24924.94	2200.00	-2200.00

SUBL WILLIAM BROTHER
PO#462967

CPSFT

PARTS: 15009.42 LABOR: 2460.00 OTHER: 80.00 TOTAL LINE A: 17549.42

CHECKED OIL AND COOLANT O.K. CHECKED FOR BLACK FUEL , CHECKED FOR
CODES , RAN INJECTOR ACTUATION PRESSURE TEST O.K. , NOTICED BREATHING
HEAVY BLOW BY, RAN CYL CUT OUT TEST ALL CYL , SMOKE CLEARED UP SOME WHAT
, CALLED CUST , GOT O.K. TO REMOVE CYL HEAD , REMOVE NESS COMPONENTS TO

When wheels are removed from a vehicle, during a repair, it is the CUSTOMER'S
responsibility to re-torque lug nuts at 150 miles of use.
O'Connor Motor Company will perform this operation at no charge.

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
DISCOUNTS	
SALES TAX	
PLEASE PAY THIS AMOUNT	



THANK YOU
FOR CHOOSING
O'CONNOR MOTOR COMPANY
FOR YOUR
SERVICE NEEDS.

CUSTOMER SIGNATURE

CUSTOMER COPY

CUSTOMER #: 1477

228191



299 Warren Avenue
Portland, ME 04103
Tel. (207) 797-7837
1-800-464-6225



INVOICE

PORTLAND SAFE CONSULTING & DESIGN IN
3 MALLISON FALLS ROAD
WINDHAM, ME 04062
HOME:207-893-1800 CONT:N/A
BUS: CELL:

PAGE 2

www.oconnorgmc.com

SERVICE ADVISOR: 309 GEORGE CORLISS

COLOR	YEAR	MAKE/MODEL	VIN	LICENSE	MILEAGE IN/ OUT	TAG	
	03	STERLING ACTERRA	2FZACFAK83AL99671		179529/179529		
IN SERVICE DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	RATE	PAYMENT	INV. DATE
16AUG11 DD			19:00 16AUG11	PHIL	93.00	CHG	31AUG11
R.O. OPENED		READY	OPTIONS: DLR:33611 ENG:Cat 3126/CFE DSL 7.2L				

06:38 16AUG11	10:48 31AUG11	LIST	NET	TOTAL
---------------	---------------	------	-----	-------

REMOVE CYL HEAD FOUND #2 CYL SCORED , CALLED AND TALKED WITH PHIL ,
ORDERED REMAN ENGINE , REMOVE HOOD ASSEMBLY , RAD ASSEMBLY AND NESS
COMPONANTS ,TO REMOVE OLD ENGINE , RE-ASSEMBLED CORE ,INSTALL REMAN
ENGINE AND REPLACE CLUTCH ASSEMBLY , REPLACE BLOCK HEATER ,SWAPPED
OVER NEEDED PARTS FROM OLD ENGINE TO NEW ENGINE ,FLUSHED OUT RAD ,
PRIMED UP FUEL SYSTEM ,REPLACE HEATER PIPE FILLED WITH COOLANT AND OIL
STARTED ENGINE , RAN IT UP TO TEMP , ROAD TESTED ,CHECKED FOR ANY LEAKS
, ALL O.K. .

CUSTOMER PAY MISC. SUPPLIES FOR REPAIR ORDER 20.00

***** O'CONNOR MOTOR COMPANY *****
***** SERVICE MANAGER - JAMIE PURDY *****
***** PARTS AND SERVICE HOURS *****
***** MON - THU 7AM - 6PM FRI 7AM - 5PM *****
***** SAT 8:00 AM - 12:00 NOON *****
***** PLEASE INQUIRE ABOUT OUR " NEW " *****
***** QUICK LUBE PLUS PROGRAM *****



THANK YOU

When wheels are removed from a vehicle, during a repair, it is the CUSTOMER'S responsibility to re-torque lug nuts at 150 miles of use.
O'Connor Motor Company will perform this operation at no charge.

DESCRIPTION	TOTALS
LABOR AMOUNT	2460.00
PARTS AMOUNT	15009.42
GAS, OIL, LUBE	0.00
SUBLET AMOUNT	80.00
MISC. CHARGES	20.00
TOTAL CHARGES	17569.42
DISCOUNTS	0.00
SALES TAX	861.47
PLEASE PAY THIS AMOUNT	18430.89



THANK YOU
FOR CHOOSING
O'CONNOR MOTOR COMPANY
FOR YOUR
SERVICE NEEDS.

CUSTOMER SIGNATURE

CUSTOMER COPY